Work Order ID 93454

November-15-12 8:55:15 AM

93454

Item ID: D4728-047 **Accept** *N900040100* **Setup Start** *NS1*

Revision ID: **Stop** *NS2*

Item Name: Advisory Light. Fwd

Start Date: 15/11/2012 **Start Qty:** 2.00 *2*

Required Date: 29/11/2012 **Req'd Qty:** 2.00 *2*

Reference:

Cust Item ID:

Customer:

Run Start *NR1*

Stop *NR2*

Approvals: **Process Plan:** ML5 **Date:** 12-11-15 **Tooling:** **Date:**

QC: **Date:** **SPC (Y/N):** **Date:**

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	**Revision Nbr**								
D4728	A								
110		0.00							
110									
Outsource8	**Memo**	0.00							
Outsource process- Eagle	Issue P/O to Eagle : 18452 Manufacture as per dwg Certificate of conformity required					CX	12/11/20	(2)	
120	Receive & Inspect for Damage & Mat'l Certs	0.00							
120									
Packaging	**Memo**	0.00							
Packaging	Inspect and check certificate of conformity					2x		SD 12-12-27	
130	QC 100% Inspect kits for completeness	0.00							
130									
QC	**Memo**	0.00							
Quality Control						2			

DAS 15 12-89 13 01 05

DQA: _____ Date: _____

NCR: Yes / No

WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: Date:

Work Order: _____

Part No. _____

NCR No. _____

DISPOSITION

- Rework ☐
- Scrap ☐
- Use-as-is ☐
- Work Order Update ☐

AGAINST DEPARTMENT/PROCESS

- Skid-tube ☐
- Machining ☐
- Thermoforming ☐
- Large Fab ☐
- Crosstube ☐
- Small Fab ☐
- Finishing ☐
- Composite ☐
- Water Jet ☐
- Prod. Eng. Coor. ☐
- Rec/Store/Packaging ☐
- Supplier ☐
- Engineering ☐
- Quality ☐
- Other ☐

Root Cause		Date	Step	Qty	Description of work order update or Non-conformance	Initial Chief Eng	Action Description	Sign & Date	Verification	QC Inspector
Doc/Data	☐									
Equip/Tooling	☐									
Operator	☐									
Material	☐									
Setup	☐									
Other	☐									
Process	☐									
Supplier	☐									
Training	☐									
Unapproved	☐									

FAULT CATEGORY

Landing Gear

- ☐ Bending
- ☐ Centre Not Concentric to O/S
- ☐ Cracks
- ☐ Crushed/Crimped
- ☐ Cuffs
- ☐ Heat Treat
- ☐ Inspection Strip in Tube
- ☐ Ripples in Bend
- ☐ Torque Waves in Extrusion
- ☐ Turning Sequence
- ☐ Wave/Twist in Tube

General

- ☐ Bend
- ☐ BOM/Route
- ☐ Broken/Damaged
- ☐ Burrs
- ☐ Contamination
- ☐ Countersink
- ☐ Cut Too Short
- ☐ Drill Holes
- ☐ Drawing
- ☐ Finish
- ☐ Folio
- ☐ Grain
- ☐ Hardware
- ☐ Inspection Incomplete
- ☐ Instructions Incomplete/Unclear
- ☐ Maintenance
- ☐ Mislabeled
- ☐ Misread
- ☐ Offset
- ☐ Out of Calibration
- ☐ Out of Sequence
- ☐ Outside Dimensions
- ☐ Ovalized
- ☐ Over/Under tolerance
- ☐ Part Incorrect
- ☐ Part Lost/Missing
- ☐ Part Moved
- ☐ Positioned Wrong
- ☐ Power Loss/Surge
- ☐ Pressure/Forced
- ☐ Temperature/Cure
- ☐ Weld
- ☐ Wrong Stock Pulled
- ☐ Other

Work Order ID 93454

November-15-12 8:55:15 AM

93454

Item ID: D4728-047 **Accept** *N9000040100* **Setup Start** *NS1*

Revision ID: **Stop** *NS2*

Item Name: Advisory Light, Fwd

Start Date: 15/11/2012 **Start Qty:** 2.00 *2*

Required Date: 29/11/2012 **Req'd Qty:** 2.00 *2*

Reference:

Cust Item ID:

Customer:

Approvals: **Process Plan:** _____ **Date:** _____ **Tooling:** _____ **Date:** _____ **Run Start** *NR1*

QC: _____ **Date:** _____ **SPC (Y/N):** _____ **Date:** _____ **Stop** *NR2*

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
140	Identify as per dwg & Stock Location: ST120	0.00				2K			SP
140									13-01-03
Packaging	**Memo**	0.00							
Packaging									
150	QC21- Final Inspection - Work Order Release	0.00							13/1/10
150									
QC	**Memo**	0.00							
Quality Control									

13-01-4

DQA: _____ Date: _____

NCR: Yes / No

WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: Date:

Work Order: _____

Part No. _____

NCR No. _____

DISPOSITION

Rework ☐
Scrap ☐
Use-as-is ☐
Work Order Update ☐

AGAINST DEPARTMENT/PROCESS

Skid-tube ☐	Crosstube ☐	Water Jet ☐	Engineering ☐				
Machining ☐	Small Fab ☐	Prod. Eng. Coor. ☐	Quality ☐				
Thermoforming ☐	Finishing ☐	Rec/Store/Packaging ☐	Other ☐				
Large Fab ☐	Composite ☐	Supplier ☐	☐				

Root Cause		Date	Step	Qty	Description of work order update or Non-conformance	Initial Chief Eng	Action Description	Sign & Date	Verification	QC Inspector
Doc/Data	☐									
Equip/Tooling	☐									
Operator	☐									
Material	☐									
Setup	☐									
Other	☐									
Process	☐									
Supplier	☐									
Training	☐									
Unapproved	☐									

FAULT CATEGORY

Landing Gear

- ☐ Bending
- ☐ Centre Not Concentric to O/S
- ☐ Cracks
- ☐ Crushed/Crimped
- ☐ Cuffs
- ☐ Heat Treat
- ☐ Inspection Strip in Tube
- ☐ Ripples in Bend
- ☐ Torque Waves in Extrusion
- ☐ Turning Sequence
- ☐ Wave/Twist in Tube

General

- ☐ Bend
- ☐ BOM/Route
- ☐ Broken/Damaged
- ☐ Burrs
- ☐ Contamination
- ☐ Countersink
- ☐ Cut Too Short
- ☐ Drill Holes
- ☐ Drawing
- ☐ Finish
- ☐ Folio
- ☐ Grain
- ☐ Hardware
- ☐ Inspection Incomplete
- ☐ Instructions Incomplete/Unclear
- ☐ Maintenance
- ☐ Mislabeled
- ☐ Misread
- ☐ Offset
- ☐ Out of Calibration
- ☐ Out of Sequence
- ☐ Outside Dimensions
- ☐ Ovalized
- ☐ Over/Under tolerance
- ☐ Part Incorrect
- ☐ Part Lost/Missing
- ☐ Part Moved
- ☐ Positioned Wrong
- ☐ Power Loss/Surge
- ☐ Pressure/Forced
- ☐ Temperature/Cure
- ☐ Weld
- ☐ Wrong Stock Pulled
- ☐ Other

Picklist Print

November-15-12 8:55:18 AM

Work Order ID: 93454

93454

Parent Item: D4728-047

D4728-047

Parent Item Name: Advisory Light, Fwd

Start Date: 15/11/2012 **Required Date:** 29/11/2012

Start Qty: 2.00 **Required Qty:** 2.00

Comments: IPP REV:A 12.11.09 NEW ISSUE DD VERF:JLM

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D4728-047P		Purchased	No				Each	0.0000		2			

D4728-047P

Advisory Light, Fwd

** 2x SP12-12-27

DQA: _____ Date: _____

NCR: Yes / No

WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: Date:

Work Order: _____

Part No. _____

NCR No. _____

DISPOSITION

Rework	☐
Scrap	☐
Use-as-is	☐
Work Order Update	☐

AGAINST DEPARTMENT/PROCESS

Skid-tube	☐	Crosstube	☐	Water Jet	☐	Engineering	☐
Machining	☐	Small Fab	☐	Prod. Eng. Coor.	☐	Quality	☐
Thermoforming	☐	Finishing	☐	Rec/Store/Packaging	☐	Other	☐
Large Fab	☐	Composite	☐	Supplier	☐		☐

Root Cause		Date	Step	Qty	Description of work order update or Non-conformance	Initial Chief Eng	Action Description	Sign & Date	Verification	QC Inspector
Doc/Data	☐									
Equip/Tooling	☐									
Operator	☐									
Material	☐									
Setup	☐									
Other	☐									
Process	☐									
Supplier	☐									
Training	☐									
Unapproved	☐									

FAULT CATEGORY

Landing Gear

☐	Bending
☐	Centre Not Concentric to O/S
☐	Cracks
☐	Crushed/Crimped.
☐	Cuffs
☐	Heat Treat
☐	Inspection Strip in Tube
☐	Ripples in Bend
☐	Torque Waves in Extrusion
☐	Turning Sequence
☐	Wave/Twist in Tube

General


☐	Bend
☐	BOM/Route
☐	Broken/Damaged
☐	Burrs
☐	Contamination
☐	Countersink
☐	Cut Too Short
☐	Drill Holes
☐	Drawing
☐	Finish
☐	Folio

☐	Grain
☐	Hardware
☐	Inspection Incomplete
☐	Instructions Incomplete/Unclear
☐	Maintenance
☐	Mislabeled
☐	Misread
☐	Offset
☐	Out of Calibration
☐	Out of Sequence
☐	Outside Dimensions

☐	Ovalized
☐	Over/Under tolerance
☐	Part Incorrect
☐	Part Lost/Missing
☐	Part Moved
☐	Positioned Wrong
☐	Power Loss/Surge

☐	Pressure/Forced
☐	Temperature/Cure
☐	Weld
☐	Wrong Stock Pulled
☐	Other

LIST OF MATERIALS					
QTY PER		ITEM	PART NUMBER	DESCRIPTION	SUPPLIER
	1	1	IS5083	ADVISORY LIGHTS	BIRK AEROSYSTEM
	1	2	1-480305-0	CONNECTOR	TYCO ELECTRONICS
	A/R (3)	3	60618-1	CONTACTS	TYCO ELECTRONICS
	A/R (28)	4	XPF-1/4	EXPANDABLE SLEEVING	EDMO



D4728-047 ADVISORY LIGHT (FWD)

SHOP COPY
RETURN TO
ENGINEERING
NO CONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
STOCK ORDER
93454 MCJ
12-11-15

RELEASED
2012-11-05

NOTES:

1. ALL NEW UNSHIELDED WIRE USE M22759/41-xx-9 TYPE WIRE UNLESS OTHERWISE SPECIFIED (M22759/41-XX-X IS NOT INTENDED TO BE USED IN SOLDER APPLICATIONS, SOLDERABILITY CAN BE ACHEIVED WITH THE PROPER SOLDER. USE CRIMP SPLICES FOR REPAIR).
2. ALL NEW TWISTED SHIELDED CABLE USE M27500-xxTGxT14 TYPE CABLE UNLESS OTHERWISE SPECIFIED.
3. ALL WIRES 20 AWG UNLESS OTHERWISE SPECIFIED.
4. IDENTIFY/CODE ALL WIRES AND CABLES IN ACCORDANCE WITH 39-A-AWDP-00-X WIRING DATA PUBLICATION.
5. KEEP ALL JUMPERS, LOGIC STRAP, POWER, CHASSIS AND SIGNAL GROUND WIRES AS SHORT AS POSSIBLE.
6. ALL SPLICES MUST CONFORM TO MIL-S-81824, OR EQUIVALENT AND BE INSTALLED IN ACCORDANCE WITH 39-A-AWDP-00-X WIRING DATA PUBLICATION.
7. ALL TERMINALS TO BE INSTALLED IN ACCORDANCE WITH 39-A-AWDP-00-X WIRING DATA PUBLICATION.
8. ALL ELECTRICAL GROUNDING AND BONDING TO BE INSTALLED IN ACCORDANCE WITH 39-A-AWDP-00-X WIRING DATA PUBLICATION.
9. ALL CONNECTORS TO BE INSTALLED IN ACCORDANCE WITH 39-A-AWDP-00-X WIRING DATA PUBLICATION.
10. ENSURE ALL UNUSED CONNECTOR CONTACTS ARE FILLED WITH SPARE PINS/SOCKETS OR PLASTIC GROMMET SEALING PLUGS.
11. A DOT (•) BEFORE A CONNECTOR CONTACT LETTER DENOTES LOWER CASE.
12. UNITS: INCHES UNLESS OTHERWISE NOTED.
13. IDENTIFY CONNECTORS WITH SHRINK SLEEVE LABELS.

DESIGN		**DART AEROSPACE LTD** HAWKESBURY, ONTARIO, CANADA
DRAWN		
CHECKED		DRAWING NO. D4728 REV. A
MFG. APPR.		SHEET 7 OF 15
APPROVED		TITLE UTILITY INTERIOR WIRING HARNESS SCALE NTS
DE APPR.		
DATE 12.09.26		COPYRIGHT © 2012 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

EAGLE COPTERS — INNOVATIVE HELICOPTER SOLUTIONS

PACKING SLIP

DATE: 18 Dec 12

FROM: Eagle Copters Maintenance Ltd.
823 McTavish Rd. NE
Calgary, AB, Canada
T2E 7G9

SHIP TO : DART Aerospace Ltd.
1270 Aberdeen St.
Hawkesbury, ON, K6A 1K7

ITEM NO.	QUANTITY ORDERED	QUANTITY SHIPPED	BACK ORDERED	PART NUMBER	BATCH / S/N NUMBER	CUSTOMER PURCHASE ORDER	EAGLE WORK ORDER	DESCRIPTION
1	2	2	0	D4728-041P		PO18458	49780	See attached work report for parts used to assemble harnesses. Traceability of product to Eagle stock
2	2	2	0	D4728-042P		PO18458	49780	
3	2	2	0	D4728-043P		PO18458	49780	
4	2	2	0	D4728-044P		PO18458	49780	
5	2	2	0	D4728-045P		PO18458	49780	
6	2	2	0	D4728-046P		PO18458	49780	
7	2	2	0	D4728-047P		PO18458	49780	
8	2	2	0	D4728-049P		PO18458	49780	
9	2	2	0	D4728-051P		PO18458	49780	
10	2	2	0	D4728-053P		PO18458	49780	
11	2	2	0	D4728-055P		PO18458	49780	
12	2	2	0	D4728-057P		PO18458	49780	

CERTIFICATE OF CONFORMANCE

[X] I HEREBY CERTIFIY THAT THE AIRCRAFT PARTS DESCRIBED HEREON WERE ACQUIRED FROM A SOURCE OF SUPPLY THAT IS CONSISTENT WITH THE CONDITIONS UNDER WHICH TRANSPORT CANADA APPROVED DISTRIBUTOR APPROVAL NUMBER 6-81 HAS BEEN GRANTED

AUTHORIZED INSPECTOR: _____

TCCA APPROVAL NO.: 6-81

EAGLE COPTERS — INNOVATIVE HELICOPTER SOLUTIONS

PACKING SLIP

DATE: 18 Dec 12

FROM: Eagle Copters Maintenance Ltd.
823 McTavish Rd. NE
Calgary, AB, Canada
T2E 7G9

SHIP TO : DART Aerospace Ltd.
1270 Aberdeen St.
Hawkesbury, ON, K6A 1K7

ITEM NO.	QUANTITY ORDERED	QUANTITY SHIPPED	BACK ORDERED	PART NUMBER	BATCH / S/N NUMBER	CUSTOMER PURCHASE ORDER	EAGLE WORK ORDER	DESCRIPTION
13	2	2	0	D4728-059P		PO18458	49780	See attached work report for parts used to assemble harnesses. Traceability of product to Eagle stock
14	2	2	0	D4728-061P		PO18458	49780	
15	2	2	0	D4728-063P		PO18458	49780	

[x] I HEREBY CERTIFIY THAT THE AIRCRAFT PARTS DESCRIBED HEREON WERE ACQUIRED FROM A SOURCE OF SUPPLY THAT IS CONSISTENT WITH THE CONDITIONS UNDER WHICH TRANSPORT CANADA APPROVED DISTRIBUTOR APPROVAL NUMBER 6-81 HAS BEEN GRANTED

AUTHORIZED INSPECTOR: _____

TCCA APPROVAL NO.: 6-81

Eagle Copters Maintenance Ltd

WORK REPORT.

Work Order Number: 49780 Modify AW139 Wiring Harnesses

This Work Report forms part of this aircraft's permanent technical records - **DO NOT DESTROY.**

Item: 1 AW139 Utility Interior Wiring Harnesses

Squawk: 1.1

Discrepancy:
Assembly L/H Cabin
Speaker #1 Harness IAW
DWG D4728-041P

Resolution:
Cabin speaker harness
assembly assembled per
DWG IAW DWG4728-041P

1.1 Work Done By: Wendell McGrath

The maintenance described above has been performed in accordance with the applicable standards of airworthiness.
AMO 6-81 Signature: Graeme Rowe on 12/21/2012

Parts:

Part Number	Description	Serial Number	Lot Number	Condition	Qty
640911-1	SPADE SOCKET .205 22-18AWG		LT-09-009742	New	2
M24308/4-2Z	CONNECTOR		LT-12-013656	New	1
M39029/64-369	PIN		LT-07-008635	New	5
M85049/48-2-2F	BACKSHELL		LT-12-019637	New	1
M24308/26-1F	FEMALE SCREW JACK		LT-12-011949	New	1
1-480303-0	CONNECTOR		LT-09-002901	New	1
60617-1	CONTACT		LT-12-018860	New	3
M22759/41-20-9	WIRE		LT-12-017365	New	2
M22759/41-20-9	WIRE		LT-12-017365	New	3
M27500-20TG2T14	WIRE		LT-05-003764	New	2
XPF-1/4	EXPANDABLE SLEEVING		LT-12-008826	New	2

Squawk: 1.2

Discrepancy:
Assembly L/H Cabin
Speaker #1 Harness IAW
DWG D4728-041P

Resolution:
Cabin speaker harness
assembly assembled per
DWG IAW DWG4728-041P

1.2 Work Done By: Wendell McGrath

The maintenance described above has been performed in accordance with the applicable standards of airworthiness.
AMO 6-81 Signature: Graeme Rowe on 12/21/2012

Parts:

Part Number	Description	Serial Number	Lot Number	Condition	Qty
640911-1	SPADE SOCKET .205 22-18AWG		LT-09-009742	New	2
M24308/4-2Z	CONNECTOR		LT-12-013656	New	1
M39029/64-369	PIN		LT-07-008635	New	5
M85049/48-2-2F	BACKSHELL		LT-12-019638	New	1
M24308/26-1F	FEMALE SCREW JACK		LT-12-011949	New	1
1-480303-0	CONNECTOR		LT-09-002901	New	1
60617-1	CONTACT		LT-12-018855	New	3
M22759/41-20-9	WIRE		LT-12-017365	New	5
M27500-20TG2T14	WIRE		LT-05-003764	New	2
XPF-1/4	EXPANDABLE SLEEVING		LT-12-008826	New	2

Work Order Number: 49780 Modify AW139 Wiring Harnesses

This Work Report forms part of this aircraft's permanent technical records - **DO NOT DESTROY**.

Squawk: 1.3

Discrepancy:
Assembly R/H Cabin
Speaker #1 Harness IAW
DWG D4728-042P

Resolution:
Sperker harness assembly
assembled per IAW DWG
D4728-042P

1.3 Work Done By: Wendell McGrath

The maintenance described above has been performed in accordance with the applicable standards of airworthiness.
AMO 6-81 Signature: Graeme Rowe on 12/21/2012

Parts:

Part Number	Description	Serial Number	Lot Number	Condition	Qty
640911-1	SPADE SOCKET .205 22-18AWG		LT-09-009742	New	2
M24308/4-2Z	CONNECTOR		LT-12-013656	New	1
M39029/64-369	PIN		LT-07-008635	New	2
M85049/48-2-2F	BACKSHELL		LT-12-019639	New	1
M24308/26-1F	FEMALE SCREW JACK		LT-12-011949	New	1
M27500-20TG2T14	WIRE		LT-05-003764	New	2

Squawk: 1.4

Discrepancy:
Assembly R/H Cabin
Speaker #1 Harness IAW
DWG D4728-042P

Resolution:
Sperker harness assembly
assembled per DWG
D4728-042P

1.4 Work Done By: Wendell McGrath

The maintenance described above has been performed in accordance with the applicable standards of airworthiness.
AMO 6-81 Signature: Graeme Rowe on 12/21/2012

Parts:

Part Number	Description	Serial Number	Lot Number	Condition	Qty
640911-1	SPADE SOCKET .205 22-18AWG		LT-09-009742	New	2
M24308/4-2Z	CONNECTOR		LT-12-013656	New	1
M39029/64-369	PIN		LT-07-008635	New	2
M85049/48-2-2F	BACKSHELL		LT-12-019640	New	1
M24308/26-1F	FEMALE SCREW JACK		LT-12-011949	New	1
M27500-20TG2T14	WIRE		LT-05-003764	New	2

Work Order Number: 49780 Modify AW139 Wiring Harnesses

This Work Report forms part of this aircraft's permanent technical records - **DO NOT DESTROY**.

Squawk: 1.5

Discrepancy:
Assembly L/H Cabin
Speaker #2 Harness IAW
DWG D4728-043P

Resolution:
Cabin speaker harness
assembly assembled per
IAW DWG D4728-043P

1.5 Work Done By: Wendell McGrath

The maintenance described above has been performed in accordance with the applicable standards of airworthiness.
AMO 6-81 Signature: Graeme Rowe on 12/21/2012

Parts:

Part Number	Description	Serial Number	Lot Number	Condition	Qty
640911-1	SPADE SOCKET .205 22-18AWG		LT-09-009742	New	2
M24308/4-2Z	CONNECTOR		LT-12-013656	New	1
M39029/64-369	PIN		LT-07-008635	New	2
M85049/48-2-2F	BACKSHELL		LT-12-019641	New	1
M24308/26-1F	FEMALE SCREW JACK		LT-12-011949	New	1
M27500-20TG2T14	WIRE		LT-05-003764	New	2

Squawk: 1.6

Discrepancy:
Assembly L/H Cabin
Speaker #2 Harness IAW
DWG D4728-043P

Resolution:
Cabin speaker harness
assembly assembled per
IAW DWG D4728-043P

1.6 Work Done By: Wendell McGrath

The maintenance described above has been performed in accordance with the applicable standards of airworthiness.
AMO 6-81 Signature: Graeme Rowe on 12/21/2012

Parts:

Part Number	Description	Serial Number	Lot Number	Condition	Qty
640911-1	SPADE SOCKET .205 22-18AWG		LT-09-009742	New	2
M24308/4-2Z	CONNECTOR		LT-12-013656	New	1
M39029/64-369	PIN		LT-07-008635	New	2
M85049/48-2-2F	BACKSHELL		LT-12-019642	New	1
M24308/26-1F	FEMALE SCREW JACK		LT-12-011949	New	1
M27500-20TG2T14	WIRE		LT-05-003764	New	2

Work Order Number: 49780 Modify AW139 Wiring Harnesses

This Work Report forms part of this aircraft's permanent technical records - **DO NOT DESTROY**.

Squawk: 1.7

Discrepancy:
Assembly R/H Cabin
Speaker #2 Harness IAW
DWG D4728-044P

Resolution:
Cabin speaker harness
assembly assembled per
IAW DWG D4728-044P

1.7 Work Done By: Wendell McGrath

The maintenance described above has been performed in accordance with the applicable standards of airworthiness.
AMO 6-81 Signature: Graeme Rowe on 12/21/2012

Parts:

Part Number	Description	Serial Number	Lot Number	Condition	Qty
640911-1	SPADE SOCKET .205 22-18AWG		LT-09-009742	New	2
M24308/4-2Z	CONNECTOR		LT-12-019267	New	1
M39029/64-369	PIN		LT-07-008635	New	2
M85049/48-2-2F	BACKSHELL		LT-12-019643	New	1
D20418-2	LOCK		LT-08-010449	New	1
M27500-20TG2T14	WIRE		LT-05-003764	New	2

Squawk: 1.8

Discrepancy:
Assembly R/H Cabin
Speaker #2 Harness IAW
DWG D4728-044P

Resolution:
Cabin speaker harness
assembly assembled per
IAW DWG D4728-044P

1.8 Work Done By: Wendell McGrath

The maintenance described above has been performed in accordance with the applicable standards of airworthiness.
AMO 6-81 Signature: Graeme Rowe on 12/21/2012

Parts:

Part Number	Description	Serial Number	Lot Number	Condition	Qty
640911-1	SPADE SOCKET .205 22-18AWG		LT-09-009742	New	2
M24308/4-2Z	CONNECTOR		LT-12-019269	New	1
M39029/64-369	PIN		LT-07-008635	New	2
M85049/48-2-2F	BACKSHELL		LT-12-019644	New	1
D20418-2	LOCK		LT-10-005971	New	1
M27500-20TG2T14	WIRE		LT-05-003764	New	2

Work Order Number: 49780 Modify AW139 Wiring Harnesses

This Work Report forms part of this aircraft's permanent technical records - **DO NOT DESTROY**.

Squawk: 1.9

Discrepancy:
Assembly L/H Cabin
Speaker #3 Harness IAW
DWG D4728-045P

Resolution:
Cabin speaker harness
assembly assembled per
IAW DWG D4728-045P

1.9 Work Done By: Wendell McGrath

The maintenance described above has been performed in accordance with the applicable standards of airworthiness.
AMO 6-81 Signature: Graeme Rowe on 12/21/2012

Parts:

Part Number	Description	Serial Number	Lot Number	Condition	Qty
640911-1	SPADE SOCKET .205 22-18AWG		LT-09-009742	New	2
M24308/4-2Z	CONNECTOR		LT-12-019265	New	1
M39029/64-369	PIN		LT-07-008635	New	5
M85049/48-2-2F	BACKSHELL		LT-12-019645	New	1
D20418-2	LOCK		LT-10-005971	New	1
1-480303-0	CONNECTOR		LT-09-002901	New	1
60617-1	CONTACT		LT-12-018857	New	3
M22759/41-20-9	WIRE		LT-12-017365	New	5
M27500-20TG2T14	WIRE		LT-05-003764	New	2
XPF-1/4	EXPANDABLE SLEEVING		LT-12-008826	New	2

Squawk: 1.10

Discrepancy:
Assembly L/H Cabin
Speaker #3 Harness IAW
DWG D4728-045P

Resolution:
Cabin speaker harness
assembly assembled per
IAW DWG D4728-045P

1.10 Work Done By: Wendell McGrath

The maintenance described above has been performed in accordance with the applicable standards of airworthiness.
AMO 6-81 Signature: Graeme Rowe on 12/21/2012

Parts:

Part Number	Description	Serial Number	Lot Number	Condition	Qty
640911-1	SPADE SOCKET .205 22-18AWG		LT-09-009742	New	2
M24308/4-2Z	CONNECTOR		LT-12-019268	New	1
M39029/64-369	PIN		LT-07-008635	New	5
M85049/48-2-2F	BACKSHELL		LT-12-019646	New	1
D20418-2	LOCK		LT-10-005971	New	1
1-480303-0	CONNECTOR		LT-09-002901	New	1
60617-1	CONTACT		LT-12-018858	New	3
M22759/41-20-9	WIRE		LT-12-017365	New	5
M27500-20TG2T14	WIRE		LT-05-003764	New	2
XPF-1/4	EXPANDABLE SLEEVING		LT-12-008826	New	2

Work Order Number: 49780 Modify AW139 Wiring Harnesses

This Work Report forms part of this aircraft's permanent technical records - **DO NOT DESTROY.**

Squawk: 1.11
Discrepancy:
Assembly R/H Cabin
Speaker #3 Harness IAW
DWG D4728-046P

Resolution:
Cabin speaker harness
assembly assebled per IAW
DWG D4728-046P

1.11 Work Done By: Wendell McGrath

The maintenance described above has been performed in accordance with the applicable standards of airworthiness.
AMO 6-81 Signature: Graeme Rowe on 12/21/2012

Parts:

Part Number	Description	Serial Number	Lot Number	Condition	Qty
640911-1	SPADE SOCKET .205 22-18AWG		LT-09-009742	New	2
M24308/4-2Z	CONNECTOR		LT-12-019270	New	1
M39029/64-369	PIN		LT-07-008635	New	2
M85049/48-2-2F	BACKSHELL		LT-12-019647	New	1
D20418-2	LOCK		LT-10-005971	New	1
M27500-20TG2T14	WIRE		LT-05-003764	New	2

Squawk: 1.12
Discrepancy:
Assembly R/H Cabin
Speaker #3 Harness IAW
DWG D4728-046P

Resolution:
Cabin speaker harness
assembly assembled per
IAW DWG D4728-046P

1.12 Work Done By: Wendell McGrath

The maintenance described above has been performed in accordance with the applicable standards of airworthiness.
AMO 6-81 Signature: Graeme Rowe on 12/21/2012

Parts:

Part Number	Description	Serial Number	Lot Number	Condition	Qty
640911-1	SPADE SOCKET .205 22-18AWG		LT-09-009742	New	2
M24308/4-2Z	CONNECTOR		LT-12-019266	New	1
M39029/64-369	PIN		LT-07-008635	New	2
M85049/48-2-2F	BACKSHELL		LT-12-019648	New	1
D20418-2	LOCK		LT-10-005971	New	1
M27500-20TG2T14	WIRE		LT-05-003764	New	2

Work Order Number: 49780 Modify AW139 Wiring Harnesses

This Work Report forms part of this aircraft's permanent technical records - **DO NOT DESTROY**.

Squawk: 1.13

Discrepancy:
Assemble Advisory Light
FWD Harness IAW DWG
D4728-047P

Resolution:
Harness assembly
assembled per DWG
D4728-047P

1.13 Work Done By: Wendell McGrath

The maintenance described above has been performed in accordance with the applicable standards of airworthiness.
AMO 6-81 Signature: Graeme Rowe on 12/21/2012

Parts:

Part Number	Description	Serial Number	Lot Number	Condition	Qty
1-480305-0	CONNECTOR		LT-12-000549	New	1
60618-1	CONTACT		LT-11-010274	New	1
60618-1	CONTACT		LT-11-007864	New	2
M22759/41-20-9	WIRE		LT-12-017365	New	8
XPF-1/4	EXPANDABLE SLEEVING		LT-12-008826	New	2

Squawk: 1.14

Discrepancy:
Assemble Advisory Light
FWD Harness IAW DWG
D4728-047P

Resolution:
Harness assembly
assembled per DWG
D4728-047P

1.14 Work Done By: Wendell McGrath

The maintenance described above has been performed in accordance with the applicable standards of airworthiness.
AMO 6-81 Signature: Graeme Rowe on 12/21/2012

Parts:

Part Number	Description	Serial Number	Lot Number	Condition	Qty
1-480305-0	CONNECTOR		LT-12-000549	New	1
60618-1	CONTACT		LT-11-007864	New	3
M22759/41-20-9	WIRE		LT-12-017365	New	8
XPF-1/4	EXPANDABLE SLEEVING		LT-12-008826	New	2

Work Order Number: 49780 Modify AW139 Wiring Harnesses

This Work Report forms part of this aircraft's permanent technical records - **DO NOT DESTROY**.

Squawk: 1.15

Discrepancy:
Assemble Advisory Light
AFT Harness IAW DWG
D4728-049P

Resolution:
Advisory light harness
assembly assembled per
IAW DWG D478-049P

1.15 Work Done By: Wendell McGrath

The maintenance described above has been performed in accordance with the applicable standards of airworthiness.
AMO 6-81 Signature: Graeme Rowe on 12/21/2012

Parts:

Part Number	Description	Serial Number	Lot Number	Condition	Qty
1-480305-0	CONNECTOR		LT-12-000549	New	1
60618-1	CONTACT		LT-11-007864	New	3
M22759/41-20-9	WIRE		LT-12-017365	New	8
XPF-1/4	EXPANDABLE SLEEVING		LT-12-008826	New	2

Squawk: 1.16

Discrepancy:
Assemble Advisory Light
AFT Harness IAW DWG
D4728-049P

Resolution:
Aft advisory light harness
assembly assembled per
IAW DWG D4728-049P

1.16 Work Done By: Wendell McGrath

The maintenance described above has been performed in accordance with the applicable standards of airworthiness.
AMO 6-81 Signature: Graeme Rowe on 12/21/2012

Parts:

Part Number	Description	Serial Number	Lot Number	Condition	Qty
1-480305-0	CONNECTOR		LT-12-000549	New	1
60618-1	CONTACT		LT-11-007864	New	3
M22759/41-20-9	WIRE		LT-12-017365	New	8
XPF-1/4	EXPANDABLE SLEEVING		LT-12-008826	New	2

Work Order Number: 49780 Modify AW139 Wiring Harnesses

This Work Report forms part of this aircraft's permanent technical records - **DO NOT DESTROY**.

Squawk: 1.17

Discrepancy:
Assemble Cabin Lights #1
Harness IAW DWG
D4728-051P

Resolution:
Cabin lights #1 harness
assembly assembled per
IAW DWG D4728-051P

1.17 Work Done By: Wendell McGrath

The maintenance described above has been performed in accordance with the applicable standards of airworthiness.
AMO 6-81 Signature: Graeme Rowe on 12/21/2012

Parts:

Part Number	Description	Serial Number	Lot Number	Condition	Qty
1-480305-0	CONNECTOR		LT-12-000549	New	1
60618-1	CONTACT		LT-11-007864	New	3
M22759/41-20-9	WIRE		LT-12-017365	New	6
XPF-1/4	EXPANDABLE SLEEVING		LT-12-008826	New	3

Squawk: 1.18

Discrepancy:
Assemble Cabin Lights #1
Harness IAW DWG
D4728-051P

Resolution:
Cabin lights #1 harness
assembly assembled per
IAW DWG D4728-051P

1.18 Work Done By: Wendell McGrath

The maintenance described above has been performed in accordance with the applicable standards of airworthiness.
AMO 6-81 Signature: Graeme Rowe on 12/21/2012

Parts:

Part Number	Description	Serial Number	Lot Number	Condition	Qty
1-480305-0	CONNECTOR		LT-12-000549	New	1
60618-1	CONTACT		LT-11-007864	New	3
M22759/41-20-9	WIRE		LT-12-017365	New	6
XPF-1/4	EXPANDABLE SLEEVING		LT-12-008826	New	3

Work Order Number: 49780 Modify AW139 Wiring Harnesses

This Work Report forms part of this aircraft's permanent technical records - **DO NOT DESTROY**.

Squawk: 1.19

Discrepancy:
Assemble Cabin Lights #2
Harness IAW DWG
D4728-053P

Resolution:
Cabin light harness
assembly assembled per
IAW DWG D4728-053P

1.19 Work Done By: Wendell McGrath

The maintenance described above has been performed in accordance with the applicable standards of airworthiness.
AMO 6-81 Signature: Graeme Rowe on 12/21/2012

Parts:

Part Number	Description	Serial Number	Lot Number	Condition	Qty
1-480305-0	CONNECTOR		LT-12-019257	New	1
60618-1	CONTACT		LT-11-007864	New	3
M22759/41-20-9	WIRE		LT-12-017365	New	6
XPF-1/4	EXPANDABLE SLEEVING		LT-12-008826	New	3

Squawk: 1.20

Discrepancy:
Assemble Cabin Lights #2
Harness IAW DWG
D4728-053P

Resolution:
Cabin lights #2 harness
assembly assembled per
IAW DWG D4728-053P

1.20 Work Done By: Wendell McGrath

The maintenance described above has been performed in accordance with the applicable standards of airworthiness.
AMO 6-81 Signature: Graeme Rowe on 12/21/2012

Parts:

Part Number	Description	Serial Number	Lot Number	Condition	Qty
1-480305-0	CONNECTOR		LT-12-019254	New	1
60618-1	CONTACT		LT-11-007864	New	3
M22759/41-20-9	WIRE		LT-12-017365	New	6
XPF-1/4	EXPANDABLE SLEEVING		LT-12-008826	New	3

Work Order Number: 49780 Modify AW139 Wiring Harnesses

This Work Report forms part of this aircraft's permanent technical records - **DO NOT DESTROY**.

Squawk: 1.21

Discrepancy:
Assemble Cabin Lights #3
Harness IAW DWG
D4728-055P

Resolution:
Cabin lights #3 harness
assembly assembled per
IAW DWG D4728-055P

1.21 Work Done By: Wendell McGrath

The maintenance described above has been performed in accordance with the applicable standards of airworthiness.
AMO 6-81 Signature: Graeme Rowe on 12/21/2012

Parts:

Part Number	Description	Serial Number	Lot Number	Condition	Qty
1-480303-0	CONNECTOR		LT-09-002901	New	1
60617-1	CONTACT		LT-12-018863	New	2
M22759/41-20-9	WIRE		LT-12-017365	New	6
XPF-1/4	EXPANDABLE SLEEVING		LT-12-008824	New	3

Squawk: 1.22

Discrepancy:
Assemble Cabin Lights #3
Harness IAW DWG
D4728-055P

Resolution:
Cabin lights #3 harness
assembly assembled per
IAW DWG D4728-055P

1.22 Work Done By: Wendell McGrath

The maintenance described above has been performed in accordance with the applicable standards of airworthiness.
AMO 6-81 Signature: Graeme Rowe on 12/21/2012

Parts:

Part Number	Description	Serial Number	Lot Number	Condition	Qty
1-480303-0	CONNECTOR		LT-09-002901	New	1
60617-1	CONTACT		LT-12-018862	New	2
M22759/41-20-9	WIRE		LT-12-017365	New	6
XPF-1/4	EXPANDABLE SLEEVING		LT-12-008824	New	3

Squawk: 1.23

Discrepancy:
Assmble PS7J1 Jumper
Harness IAW DWG
D4728-057P

Resolution:
Jumper harness assembly
assembled per IAW DWG
D4728-057P

1.23 Work Done By: Wendell McGrath

The maintenance described above has been performed in accordance with the applicable standards of airworthiness.
AMO 6-81 Signature: Graeme Rowe on 12/21/2012

Parts:

Part Number	Description	Serial Number	Lot Number	Condition	Qty
350781-1	CONNECTOR		LT-12-019263	New	1
350690-3	CONNECTOR		LT-12-013804	New	2
M22759/41-20-9	WIRE		LT-12-017365	New	1

Work Order Number: 49780 Modify AW139 Wiring Harnesses

This Work Report forms part of this aircraft's permanent technical records - **DO NOT DESTROY**.

Squawk: 1.24

Discrepancy:
Assmble PS7J1 Jumper
Harness IAW DWG
D4728-057P

Resolution:
Jumper assembly
assembled per DWG
D4728-057P

1.24 Work Done By: Wendell McGrath

The maintenance described above has been performed in accordance with the applicable standards of airworthiness.
AMO 6-81 Signature: Graeme Rowe on 12/21/2012

Parts:

Part Number	Description	Serial Number	Lot Number	Condition	Qty
350781-1	CONNECTOR		LT-12-019264	New	1
350690-3	CONNECTOR		LT-12-013804	New	2
M22759/41-20-9	WIRE		LT-12-017365	New	1

Squawk: 1.25

Discrepancy:
Assemble Cabin Lights
Harness IAW DWG
D4728-059P

Resolution:
Harness assembly
assembled per DWG
D4728-059P

1.25 Work Done By: Wendell McGrath

The maintenance described above has been performed in accordance with the applicable standards of airworthiness.
AMO 6-81 Signature: Graeme Rowe on 12/21/2012

Parts:

Part Number	Description	Serial Number	Lot Number	Condition	Qty
1-480303-0	CONNECTOR		LT-09-002901	New	2
60617-1	CONTACT		LT-12-018854	New	4
1-480426-0	CONNECTOR		LT-009849	New	1
60618-1	CONTACT		LT-11-007864	New	4
M22759/41-20-9	WIRE		LT-12-017365	New	9
XPF-1/4	EXPANDABLE SLEEVING		LT-12-008824	New	6

Work Order Number: 49780 Modify AW139 Wiring Harnesses

This Work Report forms part of this aircraft's permanent technical records - **DO NOT DESTROY**.

Squawk: 1.26

Discrepancy:
Assemble Cabin Lights
Harness IAW DWG
D4728-059P

Resolution:
Harness assembly
assembled per DWG
D4728-059P

1.26 Work Done By: Wendell McGrath

The maintenance described above has been performed in accordance with the applicable standards of airworthiness.
AMO 6-81 Signature: Graeme Rowe on 12/21/2012

Parts:

Part Number	Description	Serial Number	Lot Number	Condition	Qty
1-480303-0	CONNECTOR		LT-09-002901	New	2
60617-1	CONTACT		LT-12-018856	New	4
1-480426-0	CONNECTOR		LT-009849	New	1
60618-1	CONTACT		LT-11-007864	New	4
M22759/41-20-9	WIRE		LT-12-017365	New	9
XPF-1/4	EXPANDABLE SLEEVING		LT-12-008824	New	6

Squawk: 1.27

Discrepancy:
Assemble Cabin Lights
Control Relay Harness IAW
DWG D4728-061P

Resolution:
Cabin lights control relay
harness assembled per
IAW DWG D4728-061P

1.27 Work Done By: Wendell McGrath

The maintenance described above has been performed in accordance with the applicable standards of airworthiness.
AMO 6-81 Signature: Graeme Rowe on 12/21/2012

Parts:

Part Number	Description	Serial Number	Lot Number	Condition	Qty
M83536/2-024M	RELAY		LT-12-019271	New	1
M12883/45-01	SOCKET, RELAY		LT-12-001340.1	New	1
1-480424-0	CONNECTOR		LT-12-019260	New	1
60617-1	CONTACT		LT-12-018859	New	4
350781-1	CONNECTOR		LT-12-019262	New	1
350690-3	CONNECTOR		LT-12-013804	New	3
1-480305-0	CONNECTOR		LT-12-019256	New	1
60618-1	CONTACT		LT-11-007864	New	2
M22759/41-20-9	WIRE		LT-12-017365	New	11
XPF-1/4	EXPANDABLE SLEEVING		LT-12-008824	New	3

Work Order Number: 49780 Modify AW139 Wiring Harnesses

This Work Report forms part of this aircraft's permanent technical records - **DO NOT DESTROY**.

Squawk: 1.28

Discrepancy:
Assemble Cabin Lights Control Relay Harness IAW DWG D4728-061P

Resolution:
Cabin lights control relay harness assembled per IAW DWG D4728-061P

1.28 Work Done By: Wendell McGrath

The maintenance described above has been performed in accordance with the applicable standards of airworthiness.
AMO 6-81 Signature: Graeme Rowe on 12/21/2012

Parts:

Part Number	Description	Serial Number	Lot Number	Condition	Qty
M83536/2-024M	RELAY		LT-12-019250	New	1
M12883/45-01	SOCKET, RELAY		LT-12-001340.1	New	1
1-480424-0	CONNECTOR		LT-12-019259	New	1
60617-1	CONTACT		LT-12-018861	New	4
350781-1	CONNECTOR		LT-12-019261	New	1
350690-3	CONNECTOR		LT-12-013804	New	3
1-480305-0	CONNECTOR		LT-12-019255	New	1
60618-1	CONTACT		LT-11-007864	New	2
M22759/41-20-9	WIRE		LT-12-017365	New	11
XPF-1/4	EXPANDABLE SLEEVING		LT-12-008824	New	3

Squawk: 1.29

Discrepancy:
Assemble Cabin Temp Sensor Jumper Assembly Harness IAW DWG D4728-063P

Resolution:
Harness assembly assembled per DWG D4728-063P

1.29 Work Done By: Wendell McGrath

The maintenance described above has been performed in accordance with the applicable standards of airworthiness.
AMO 6-81 Signature: Graeme Rowe on 12/21/2012

Parts:

Part Number	Description	Serial Number	Lot Number	Condition	Qty
MS25036-103	TERMINAL		LT-12-019575	New	2
M22759/41-20-9	WIRE		LT-12-017365	New	1

Eagle Copters Maintenance Ltd

WORK REPORT

Work Order Number: 49780 Modify AW139 Wiring Harnesses

This Work Report forms part of this aircraft's permanent technical records - **DO NOT DESTROY.**

Squawk: 1.30

Discrepancy:
Assemble Cabin Temp
Sensor Jumper Assembly
Harness IAW DWG
D4728-063P

Resolution:
Harness assembly
assembled per DWG
D4728-063P.

1.30 Work Done By: Wendell McGrath

The maintenance described above has been performed in accordance with the applicable standards of airworthiness.
AMO 6-81 Signature: Graeme Rowe on 12/21/2012

Parts:

Part Number	Description	Serial Number	Lot Number	Condition	Qty
MS25036-103	TERMINAL		LT-12-019577	New	2
M22759/41-20-9	WIRE		LT-12-017365	New	1

* End of Report *

Eagle Copters Maintenance Ltd

823 McTavish Rd, NE
Calgary, Alberta T2E 7G9
Canada

Telephone: (403) 250-7370 Fax: (403) 250-7110

Packing Slip

December 21, 2012

Shipment number: SH#12-003986
Customer PO number: 18458
Ship To: Dart Aerospace Ltd.
1270 Aberdeen Street
Hawkesbury, ON K6A 1K7
Canada
Phone:

Ship Via: FED EX
Carrier Terms:

Waybill: 7943 7755 4495
Customer PO number: 18458

Item	Part Number	Part Description	Current Location	Qty	UOM	Serial Number	Lot Number
1	AW139 Utility Interior Wiring Harnesses	AW139 Utility Interior Wiring Harnesses	Avionics Shop	1		N/A	

Work Order Number: 49780.1

Eagle PO Number:

All Parts being sent on this packing slip have the original certification on file at Eagle Copters Ltd.

* End of Report *

>> denotes that the Packing Slip line item has already been printed.

DART aerospace
Dart Aerospace Ltd.
1270 Aberdeen Street
Hawkesbury, ON K6A 1K7
Tel: 613 632 9577
Fax: 613 632 1053

PURCHASE ORDER

Purchase Order ID PO18458

Purchase Order Date 11/20/12
PO Print Date 11/20/12

Order From : VU-EAG002

EAGLE COPTERS MAINTENANCE LTD.
823 MCTAVISH ROAD N E
CALGARY, AB T2E 7G9
CA

Contact Name		**Buyer**	Chantal Lavoie
Vendor Phone	403-250-7370	**Requisition Nbr**	
Vendor Fax		**Tax Resale Nbr**	10127-2607
Vendor Account Nbr		**Terms**	Net 30
		Currency	USD
		FOB	Destination-Collect

Ship To : DART AEROSPACE LTD 1270 ABERDEEN
HAWKESBURY, ON K6A 1K7
CANADA

FAXED 12/11/12

Line Nbr	Reference / Revision ID / Vendor Part Number	Description / Mfg ID	Req Date / Taxable	Req Qty / Unit of Measure	Ship Method	Unit Price	Extended Price
1	D4728-041P	LH Cabin Speaker #	~~11/30~~ 12/05 / Yes	2.00 / Each	FedEx PI collect	$350.0000	$700.00
		Special Inst:	AS PER DWG D4728 REV. A B93445				
2	D4728-042P	RH Cabin Speaker #1	11/30/12 / Yes	2.00 / Each	FedEx PI collect	$350.0000	$700.00
		Special Inst:	AS PER DWG D4728 REV. A B93446				
3	D4728-043P	LH Cabin Speaker #2	11/30/12 / Yes	2.00 / Each	FedEx PI collect	$350.0000	$700.00
		Special Inst:	AS PER DWG D4728 REV. A B93449				
4	D4728-044P	RH Cabin Speaker #2	11/30/12 / Yes	2.00 / Each	FedEx PI collect	$350.0000	$700.00

Sp 12-12-27.

No substitution or deviation without consent.
Certificate of Conformity or Material Certification required YES NO

Change Nbr: 1 **Change Date:** 11/20/12

DART aerospace
Dart Aerospace Ltd.
1270 Aberdeen Street
Hawkesbury, ON K6A 1K7
Tel: 613 632 9577
Fax: 613 632 1053

PURCHASE ORDER

Purchase Order ID PO18458

Purchase Order Date 11/20/12
PO Print Date 11/20/12

Order From : VU-EAG002

EAGLE COPTERS MAINTENANCE LTD.
823 MCTAVISH ROAD N E
CALGARY, AB T2E 7G9
CA

Contact Name		**Buyer**	Chantal Lavoie
Vendor Phone	403-250-7370	**Requisition Nbr**	
Vendor Fax		**Tax Resale Nbr**	10127-2607
Vendor Account Nbr		**Terms**	Net 30
		Currency	USD
		FOB	Destination-Collect

			Special Inst:	AS PER DWG D4728 REV. A B93451				
5	D4728-045P		LH Cabin Speaker #3	11/30/12 Yes	2.00 Each	FedEx PI collect	$350.0000	$700.00
			Special Inst:	AS PER DWG D4728 REV. A B93452				
6	D4728-046P		RH Cabin Speaker #3	11/30/12 Yes	2.00 Each	FedEx PI collect	$350.0000	$700.00
			Special Inst:	AS PER DWG D4728 REV. A B93453				
7	D4728-047P		Advisory Light, Fwd	11/30/12 Yes	2.00 Each	FedEx PI collect	$350.0000	$700.00
			Special Inst:	AS PER DWG D4728 REV. A B93454				
8	D4728-049P		Advisory Light, Aft	11/30/12 Yes	2.00 Each	FedEx PI collect	$350.0000	$700.00
			Special Inst:	AS PER DWG D4728 REV. A B93455				
9	D4728-051P		Cabin Lights #1	11/30/12 Yes	2.00 Each	FedEx PI collect	$350.0000	$700.00

Sp 12-12-27

No substitution or deviation without consent.
Certificate of Conformity or Material Certification required (YES) NO

Change Nbr: 1 **Change Date:** 11/20/12

DART aerospace
Dart Aerospace Ltd.
1270 Aberdeen Street
Hawkesbury, ON K6A 1K7
Tel: 613 632 9577
Fax: 613 632 1053

PURCHASE ORDER

Purchase Order ID PO18458

Purchase Order Date 11/20/12
PO Print Date 11/20/12

Order From : VU-EAG002

EAGLE COPTERS MAINTENANCE LTD.
823 MCTAVISH ROAD N E
CALGARY, AB T2E 7G9
CA

Contact Name		**Buyer**	Chantal Lavoie
Vendor Phone	403-250-7370	**Requisition Nbr**	
Vendor Fax		**Tax Resale Nbr**	10127-2607
Vendor Account Nbr		**Terms**	Net 30
		Currency	USD
		FOB	Destination-Collect

			Special Inst:	AS PER DWG D4728 REV. A B93456				
10	D4728-053P	Cabin Lights #2		11/30/12 Yes	2.00 Each	FedEx PI collect	$350.0000	$700.00
			Special Inst:	AS PER DWG D4728 REV. A B93457				
11	D4728-055P	Cabin Lights #3		11/30/12 Yes	2.00 Each	FedEx PI collect	$350.0000	$700.00
			Special Inst:	AS PER DWG D4728 REV. A B93458				
12	D4728-057P	PS7J1 Jumper		11/30/12 Yes	2.00 Each	FedEx PI collect	$350.0000	$700.00
			Special Inst:	AS PER DWG D4728 REV. A B93459				
13	D4728-059P	Cabin Lights Harness		11/30/12 Yes	2.00 Each	FedEx PI collect	$350.0000	$700.00
			Special Inst:	AS PER DWG D4728 REV. A B93460				
14	D4728-061P	Cabin Lights Control Relay		11/30/12 Yes	2.00 Each	FedEx PI collect	$350.0000	$700.00

EOP 12-12-27

No substitution or deviation without consent.
Certificate of Conformity or Material Certification required - (YES) NO

Change Nbr: 1 **Change Date:** 11/20/12

DART aerospace
Dart Aerospace Ltd.
1270 Aberdeen Street
Hawkesbury, ON K6A 1K7
Tel: 613 632 9577
Fax: 613 632 1053

PURCHASE ORDER

Purchase Order ID PO18458

Purchase Order Date 11/20/12
PO Print Date 11/20/12

Order From : VU-EAG002

EAGLE COPTERS MAINTENANCE LTD.
823 MCTAVISH ROAD N E
CALGARY, AB T2E 7G9
CA

Contact Name		**Buyer**	Chantal Lavoie
Vendor Phone	403-250-7370	**Requisition Nbr**	
Vendor Fax		**Tax Resale Nbr**	10127-2607
Vendor Account Nbr		**Terms**	Net 30
		Currency	USD
		FOB	Destination-Collect

Special Inst: AS PER DWG D4728 REV. A
B93461

15	D4728-063P	Cabin Temp Sensor Jumper Assembly	11/30/12	2.00	FedEx PI collect	$350.0000	$700.00
			Yes	Each			

Special Inst: AS PER DWG D4728 REV. A
B93462

PO Total: **$10,500.00**

SP 12-12-27

CERTIFICATE OF CONFORMITY
REQ'D UPON DELIVERY

No substitution or deviation without consent.
Certificate of Conformity or Material Certification required - (YES) NO

Change Nbr: 1 **Change Date:** 11/20/12

Chantal Lavoie

From: Graeme Rowe <growe@eaglecopters.com>
Sent: November 20, 2012 12:04 PM
To: 'Chantal Lavoie'
Subject: RE: QUOTE

Hello Chantal,

The quote is as follows

$5,250 USD per ship set, so qty 2 will be $10,500 USD

GRAEME ROWE
AVIONICS MANAGER
Toll-Free 1-800-564-6469
Tel: (403) 250-7370, Fax: (403) 250-7584
Email: growe@eaglecopters.com
www.eaglecopters.com

From: Chantal Lavoie [mailto:clavoie@dartaero.com]
Sent: Friday, November 16, 2012 6:49 AM
To: growe@eaglecopters.com
Subject: QUOTE

Hi Graeme,
Please advise price and delivery on items. Please see attached for dwd.

D4728-041 X 2 - D4635-041 -
D4728-042 X 2 D4635-042.
D4728-043 X 2 D4635-041 -
D4728-044 X 2 D4635-042.
D4728-045 X 2 D4635-043.
D4728-046 X 2 D4635-044.
D4728-047 X 2 D4634-041
D4728-049 X 2 D4634-045
D4728-051 X 2 D4634-041 -
D4728-053 X 2 D4634-043 -
D4728-055 X 2 D4634-045 -
D4728-057 X 2 ~~D4634~~ D139-816-011
D4728-059 X 2 - D4635-041
D4728-061 X 2 - D4635-043
D4728-063 X 2 ~~D4634~~
D139-816-011